

ADMINISTRATIVE INFORMATION

Shipper UMETCO MINERALS CORP
Facility _____
Address 4625 ROYAL AVE NIAGARA FALLS, N.Y.
Phone 716-278-3573

CNSI Broker J. BENDER
Radwaste Supervisor DOV HANSEN

Plant Shipment Number UMC-1-85
CNSI Control Number 85-365-2

Waste Description THORIUM LAB CHEMICALS Ra²²⁶ SOURCE

Drums--Number 1
Boxes--Number 0
Casks--Type 0

Total Activity 1.27 mCi
Total Cubic Footage 4.0

Carrier CONSOLIDATED FREIGHTWAYS
Tractor Number N/A
Trailer Number N/A
Name(s) of Driver(s) N/A } (UNION CARLIERS

Date of Departure 12/31/85
Estimated Date of Arrival 1/7/86

Plant Shipment # UMC-1-85

BROKER'S INVENTORY AND INSPECTION SURVEY OF PACKAGES

[illegible]

Survey Performed by:

E-530 #550

CAI REC MAY 16, 1986

Page 1 of 1

(CNRE - 2)

UCCNHT0002696

(Mark Boxes
on Following
Pages if not
Applicable)

CHECK LIST OF BROKER'S WORK

- 1.0 Pre-Start Load Inspection
1. Check for arrival of tractor/trailer.
 - a. Record trailer and tractor number
 - b. Record driver's name and estimate arrival time at the disposal site
 2. Conduct initial survey of trailer:
 - a. Take smears at locations indicated on survey form, read, and record levels
 - b. Record dose rates
 3. Review shipment and loading arrangements:
 - a. Number of drums and boxes
 - b. Status of paperwork/shipping documents (RSR, surveys, etc.)
 - c. Number of loaders and equipment, forklifts, dollies, etc.
 4. Initial survey of containers prior to loading:
 - a. Radioactive LSA on at least one side
 - b. Package ID number
 - c. Weight on each container over 110 lbs. (not required for LSA)
 - d. Smears taken on at least 10% of containers
 - e. General conditions of containers
 - f. Open at least 10% of absorbed oil containers
 - g. DOT 7A/Type A marking as appropriate

B
B
N/A
N/A B
B
B
N/A
B
B
B
N/A
B



5.0 Post-Loading Inspection

- [illegible]

- N/A
B
N/A
B
B
B
B
B
N/A

(Mark Box
if not
Applicable)

4.0 Completing Shipping Papers

1. Complete CNSI paperwork requirements.
 - a. CNSI inspection sheet
 - b. Survey forms
 - c. Cover sheet
 - d. Prior notification form
 - e. Certification form
2. Check completion of RSR information:
 - a. Add "Bill CNSI" to upper right corner if applicable
 - b. Check release signature on both sides at bottom
 - c. Check weight totals on last sheet for cubic feet, curies, and weight
 - d. Check wording of certification statement
3. Check completion of Bill of Lading:
 - a. Correct description of load
 - b. All information completed
 - c. Identification Code after RAM
4. Prior notification call to Hanford (509) 377-2411
5. Reproduce 6 copies of all paperwork:
 - a. Shipper copy (originals of surveys)
 - b. Broker copy (CNSI forms added)
 - c. Driver copy
 - d. US Ecology original (Copy in cab)
 - e. US Ecology--second copy in trailer (sealed in back)
 - f. US Ecology--mail
6. Have facility supervisor sign broker CNSI time sheet for charges
7. Make prior notification call to Columbia (Mark Lewis at 1-803-256-0450)

B
B
B
B n/A
B

B
B

B
B

B
B

B
B

B
B

B

NOTE: sheet 4 of 4 not Applicable (CASK/TRANS)

(CNBF-7)

PRIOR NOTIFICATION CALL SHEET

SHIPMENT OF LOW-LEVEL SOLID WASTE TO
US ECOLOGY (HANFORD, WA)
509-377-2411

Date of Call: 12/31/85
Time of Call (estimated): 1300
Name of Person Contacted: LORA

Message:

"This call is to inform you that the UMETCO MINERALS CORP.
plant at NIAGARA FALLS, N.Y., will make
a truckload shipment of 1 drums, 0 boxes of radioactive
material for burial in accordance with your license at your Hanford,
Washington, site through arrangements with Chem-Nuclear Systems, Inc.

Plant Shipment number is UMC-1-85 and CNSI Control Number is 85-365-2
Carrier is CONSOLIDATED FREIGHTWAYS
Driver's name is N/A
Trailer ID Number is N/A
Tractor Number is N/A
Date of departure is 12/31/85
Estimated date of departure is 12/31/85
Estimated date of arrival at Hanford, Washington, is 1/7/86

Additional Message

NONE

Comments of Contact

(CNBF-8)

UCCNHT0002700